

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated:

It is certified that the existing building K.R. Mangalam World School (name of the building or premises) at Block-E, Sec-59, TDI City, Kundli - 131028 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3	G+2	-	-	-	-

The building is owned/occupied by K.R. Mangalam Charitable Trust (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on 10.8.26 (date of inspection) in the presence of MR. Indu Dev Gupta (Chairman) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 10.8.2026 for a period of Two years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Visual Inspection Report
2. Accdit Report
3. NDT Report
4. Analysis & Design from structural drawings Provided by the owner.

Issued on 10.8.26 at TDI City by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : _____

Designation : _____

Name & Address of Department/ Office: _____



Aditi Kaushik
AR. ADITI KAUSHIK
B. ARCH
Reg. No. CA/2020/122545